



Patmax Union Corporation

Tel No. : 886-2-29101925, 29101927 Fax No.: 886-2-29101946
E-MAIL: patmax@ms16.hinet.net E-MAIL: patmax.corp@msa.hinet.net
URL: <http://www.patmax.com.tw> URL: <http://patmax.taiwantrade.com.tw>

RANGEROVER HOSE

Catalogue No. BA-2393-ROH
(1712)

PICTURE	CAT. NO.	PART NO.	DESCRIPTION
HOSE			
	BA-2393	PCH001110	RANGER ROVER 4.4L '03-'05 HOSE
	BA-2393	PCH001121	RANGER ROVER 4.4L '03-'05 HOSE
	BA-2393	PCH001130	RANGER ROVER 4.4L '03-'05 HOSE
	BA-2393	PCH001140	RANGER ROVER 4.4L '03-'05 HOSE
	BA-2393	PCH001150	RANGER ROVER 4.4L '03-'05 HOSE
	BA-2393	PCH001600	RANGER ROVER 4.4L '03-'05 HOSE

PICTURE	CAT. NO.	PART NO.	DESCRIPTION
HOSE			
	BA-2393	PCH000900	RANGEROVER P38 1999-2003 Hose
	BA-2393	PCH000910	RANGEROVER P38 1999-2003 Hose
	BA-2393	PCH118790	RANGEROVER P38 1999-2003 Hose
	BA-2393	PCH118820	RANGEROVER P38 1999-2003 Hose
	BA-2393	PCH118830	RANGEROVER P38 1999-2003 Hose